

CompTIA

220-801

CompTIA A+ Certification

D. 5GHz

Answer: C

OUESTION: 288

A technician has been asked to configure a printer to be shared amongst the users in a small workgroup. Each computer in the workgroup utilizes an existing wireless router for network connectivity. The printer to be configured only connects via USB. Which of the following should be implemented to share the printer so that implementation costs are kept to a minimum?

- A. Connect the printer to a computer within the workgroup and share it from that computer
- B. Connect the printer to the wireless router and assign it its own network address
- C. Connect the printer to an external hardware print server and share it amongst the workgroup
- D. Connect the printer to a USB hub that each computer in the workgroup has access to

Answer: A

QUESTION: 289

A technician has been asked to procure a video adapter solution for use in commercial graphics design and CAD/CAM system. The solution should utilize specialized drivers to provide additional system stability. Which of the following solutions would BEST meet the user's needs?

- A. Dual cards in a CrossFire configuration
- B. TV Tuner card with HDMI output options
- C. CUDA enabled line of graphics cards
- D. Dual cards in an SLI configuration

Answer: C

QUESTION: 290

In which of the following situations should an MSDS be consulted?

- A. A new cleaning solution is used
- B. The corner of a desk snaps off
- C. An office window is shattered
- D. Soda is spilled on the floor

Answer: A

QUESTION: 291

Joe, a technician, is installing a wireless inkjet printer into a small office. He wants to minimize long term issues connecting to the printer from any workstation and ensure easy access to its configuration page. Which of the following steps would ensure this?

- A. Share the printer on the directory.
- B. Plug an Ethernet cord in as well.
- C. Turn off all DHCP on the network.
- D. Configure a static IP for the printer.

Answer: D

OUESTION: 292

Anne, a technician, is asked to immediately fix a CEO's tablet that is not connecting to the network, and she realizes it is missing its static IP settings. When she returns to her desk with the tablet to research the correct settings, the CEO comes over and berates her for walking away with the equipment. Which of the following is the BEST way to handle this situation?

- A. Hand the tablet back unfixed so the CEO is immediately appeared.
- B. Politely explain the reason for removing the tablet and return it after inputting the settings.
- C. Complete the settings fix before handing the tablet to the CEO, then immediately inform her Manager.
- D. Calmly explain why she was correct for taking the tablet.

Answer: B

QUESTION: 293

Which of the following slots would MOST likely be used to install and configure a

modern RAID card?

A. PCIe

B. AGP

C. CNR

D. ISA

Answer: A

QUESTION: 294

Which of the following RAID types employs two identically sized disks and creates a mirror for data redundancy purposes?

A. RAID 0

B. RAID 1

C. RAID 1+0

D. RAID 5

Answer: B

QUESTION: 295

Which of the following 802.11 wireless standards provides a maximum of 54Mbps data transmission over an uncongested 5GHz spectrum?

A. A

B. B

C. G

D. N

Answer: A

QUESTION: 296

When replacing components inside of a computer, which of the following should be worn to prevent electro-static discharge?

- A. Safety goggles
- B. Grounding strap
- C. Safety shoes
- D. Canvas gloves

Answer: B

QUESTION: 297

Which of the following components would MAXIMIZE I/O performance of a graphic design workstation?

- A. High performance GPU.
- B. Maximum RAM
- C. Solid State Drive
- D. Multicore CPU

Answer: C

QUESTION: 298

Which of the following components needs to be maximized to improve performance in a workstation used for virtualization? (Select TWO).

- A. Network speed
- B. RAM
- C. Disk space
- D. USB ports
- E. CPU cores
- F. Video cards

Answer: B, E

QUESTION: 299

Which of the following RAM types is rated at PC2400?

- A. DDR
- B. DDR2

C. DDR3 D. SDRAM

Answer: A

QUESTION: 300

A Bluetooth printer has been installed. Which of the following MUST be performed to allow users to print from a mobile device?

- A. Enable MAC filtering B. Configure print queue C. Set static IPs
- D. Device pairing

Answer: D

For More exams visit https://killexams.com -

















